

Transition EIS: Preliminary Alternative 3

Area 4c - Well and Road Mitigations in Addition to those Identified for Alternative 2 - Area 4c

Well No.	Area No.	Well Concerns	Mitigation
B15-1659	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
B15-1660	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
Bn01-1446	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
Bn01-1445	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
Bn01-1449	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
Bn01-1453	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
B15-1658	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
B15-1652	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
B15-1653	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
B15-1654	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
B15-1655	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
B15-1662	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
B15-1656	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
B15-1657	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
B15-1661	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
Bn01-1437	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
Bn01-1434	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy

Well No.	Area No.	Well Concerns	Mitigation
Bn01-1441	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
Bn01-1442	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
Bn01-1447	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy

Road No.	Area No.	Road Concerns	Mitigation
TE101842	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101843	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101848	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101851	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101852	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101854	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101858	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101859	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101862	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101864	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101865	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101866	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101867	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101868	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101869	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy

Well No.	Area No.	Well Concerns	Mitigation
TE101870	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101871	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101901	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101902	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101907	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE101930	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE102300	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE102301	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE102302	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE102303	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy
TE102304	4c	Significant Issue 2: Impacts to Forest Road 454 (Rimrock access road) and/or Morrison Run trail system	No surface occupancy